

**From:** [Jonathan Carroll](#)  
**To:** [Moore, Gary](#)  
**Subject:** Re: Tank 16 Patch bottom  
**Date:** Tuesday, September 24, 2013 12:25:01 PM

---

I will find out all, however I need to know a final cost of repair and what you are requiring us to do. Please advise.

---

**From:** "Moore, Gary" <Moore.Gary@epa.gov>  
**To:** Jonathan Carroll <JCarroll@lazarusenergy.com>  
**Sent:** Tuesday, September 24, 2013 12:19 PM  
**Subject:** RE: Tank 16 Patch bottom

**Jonathan:**

**I looked it up and my understanding is that the slotted shell method is used to put in a double bottom. I assume that you are repairing the current bottom of Tank 16 and then putting in a double bottom. I am not exactly sure what you guys are doing.**

**I also understand that you guys took samples of the sand beneath Tank 16. Do you have any results back as of yet?**

**Thanks**

**Gary Moore**

**Federal On-Scene Coordinator**

**U.S. EPA Region 6**

**214-789-1627 cell**

**214-665-6609 office**

**[moore.gary@epa.gov](mailto:moore.gary@epa.gov)**

---

**From:** Jonathan Carroll <JCarroll@lazarusenergy.com>  
**Sent:** Tuesday, September 24, 2013 11:54 AM  
**To:** Moore, Gary  
**Subject:** Re: Tank 16 Patch bottom

No, and No.

---

**From:** "Moore, Gary" <Moore.Gary@epa.gov>  
**To:** Jonathan Carroll <JCarroll@lazarusenergy.com>  
**Sent:** Tuesday, September 24, 2013 11:53 AM  
**Subject:** RE: Tank 16 Patch bottom

**Jonathan:**

**Have you decided to replace the entire tank bottom? Did the report show that this was necessary?**



9568276

**Thanks**

**Gary Moore**

Federal On-Scene Coordinator

U.S. EPA Region 6

214-789-1627 cell

214-665-6609 office

[moore.gary@epa.gov](mailto:moore.gary@epa.gov)

---

**From:** Jonathan Carroll <JCarroll@lazarusenergy.com>

**Sent:** Tuesday, September 24, 2013 11:37 AM

**To:** Moore, Gary

**Cc:** Steven Wilson

**Subject:** Fw: Tank 16 Patch bottom

What do you want us to do? see attached.

----- Forwarded Message -----

**From:** Andrew Martin <ajm@bbbtanksvc.com>

**To:** jcarroll@lazarusenergy.com

**Cc:** bobswain@bbbtanksvc.com; 'Jacob Swain' <jacobswain@bbbtanksvc.com>;  
garythompson@bbbtanksvc.com

**Sent:** Tuesday, September 24, 2013 7:50 AM

**Subject:** Tank 16 Patch bottom

Jonathan – Please see attached changes as well as comparisons per your request. I will call and follow up this morning with you accordingly. Thanks a for your time and consideration.

Andrew "Andy" J. Martin

Director

BBB Tank Services, Inc.

162 Independence Pkwy N

Baytown, Texas 77520

Office: 832.695-2132

Fax: 281.838-8748

Cell: 832.724.3149

[ajm@bbbtanksvc.com](mailto:ajm@bbbtanksvc.com)

[www.bbbtankservices.com](http://www.bbbtankservices.com)